

ANNUAL SURVEYS.

33488

No. 152 Survey held at London Date 4th Nov^r 17th 1873
on the Composite Ship Thermopylae Master R. Kemball
 Tonnage 947 Built at Aberdeen When built 1868 8th mth
 By whom built Hood Owners Thompson & Co.
 Port belonging to Aberdeen Destined Voyage Melbourn
 If Surveyed Afloat or in Dry Dock Canal dry dock & East India Dock

Last Survey, No. 61 Port of Shanghai Classified 17. A. 1. S.S. 172

The present Condition of the

Decks	<u>good</u>	Treenails	<u>Boles</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	<u>"</u>	Breasthooks and Stems	<u>"</u>	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	<u>"</u>	Sails	<u>"</u>
Plank sheers	<u>"</u>	Keelsons	<u>"</u>	<u>"</u>	Anchors, No. of <u>3 B, 1 S, 2 K</u>	<u>"</u>
Sheerstrakes	<u>"</u>	Clamps and Shells	<u>"</u>	<u>"</u>	Cables	<u>"</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	<u>"</u>	Hawsers and Warps	<u>"</u>
Wales	<u>"</u>	Rudder	<u>efficient</u>	<u>"</u>	Standing and Running Rigging	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper	<u>9th metal</u>	When put on <u>1872</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Pat'd the Yellow Metal Sheathing, overhauled the Caulking above.
She is in good condition and entitled to

Committee's Minute 18

Character assigned 17A

remain as classed 17. A. 1.

TRW

© 2018
 R
 Foundation
 Certificate (if required)