

No. 36401 Survey held at London Date, first Survey 26th Oct. Last Survey 30th Oct. 1877

No. in Reg. Book. on the Comp. Ship "Chermophylla" Master Matheson

Tonnage 945 Built at Aberdeen When built 1868 — 8 mo

By whom built Good Owners J. Thompson Junr & Co.

Port belonging to Aberdeen Destined Voyage

If Surveyed Afloat or in Dry Dock Afloat Dry 5th & afloat (C.I. 5000)

Last Survey, No. 35833 Port of London

Classed

Year assigned.

17

Character in Register Book.

A 1

Present Condition of the

Decks Good

Waterways —

Comings —

Upper Deck Beams & Fastenings —

Lower Deck Beams & Fastenings —

Plank sheers —

Sheerstrakes —

Topboards —

Wales —

Plank (Bottom) and Counter —

Treenails See when seen Good

Breasthooks and Stems —

Transoms, Pointers, and Crutches —

Timbers of the Frame at the Openings —

Ditto ditto at other places —

Keelsons (Ballast in hold) —

Clamps and Shelves —

Ceiling —

Rudder —

Copper or Y.M. When put on —

Caulking of Bottom, Deck, & Waterways —

H.T. Len 76

S.S. Len 76

Windlass and Capstan Good

Pumps —

Boats 4 20

Masts, Yards, &c. —

Condition, how ascertained from deck

Sails Good

Anchors, No. of 30, 15 & 20

Cables —

Haucers and Warps —

Standing and Running Rigging —

Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. Metal patched; vessel recomended

in Sopsidas

This vessel appears to be in good and efficient condition, and eligible to remain as at present classed.

Committee's Minute 23rd November, 1877,

Character assigned A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)



© 2018

Lloyd's Register Foundation