

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *SH T.S.S. "RAWALPINDI"*

Rpt.

Bel

No.

9412

18373

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

1st Long

Transverse No.

23413

Depth "d"

9.58

Framing: Table No.

Description

Channel frames with revised

2nd Longitudinal No.

62226

frames as approved

Proportions

Length

11.59

Depth

Deck Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the *Revised* Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100 A.1. (Steel)** with freeboard," as recommended. The Summer freeboard of 18 ft 10 in from centre of disc to top of statutory deck line at - deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

3 dks (Stl - weather dk pt teak S.) 4th dk (Stl) in holds, 5th dk (Stl) in 1. 2. 3 holds.
 Cell D.B 461 20925 tanks at sides of tunnels 2785. F.P.T. 1305 A.P.T. 1520.
 F.K, 128.4 (Coll B.H. to weather dk). pt cm, Lloyd's Av CP.
 B. 304 F 84.

The surveyor should be requested to forward *particulars* of the *waterballast*



© 2018

Lloyd's Register
Foundation

14.9.25