

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc "BELPAMELA" Rpt. NWC No. 82473

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

1st. Long.

Transverse No. 7637Depth "d" 20.42Framing: Table No. ✓Description Bulk angle as approved.

2nd.

Longitudinal No. 23562Proportions Length 13.83
Depth =Deck Sheerstrake as approved.

Revised Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

±100A1 (Steel).

1 DK (Stl.)

Cell DB 208' 651E; FPT 129E. APT 143E.

FK. ~~4BH~~ "Intermediate bulkhead in holds dispensed with 4BH and one oil-fuel tank BH."Part CEN. hlongds A & C. P.

P 88'. B 22'. F 27'.

Machy. aft.

87B
10-3-28

© 2018

Lloyd's Register
Foundation