

5968
ANNUAL SURVEYS.

Rev 20/1/68

No. 1040 Survey held at Wm. Shields Date 24 Novr 1867
 on the Wm. Shields Master Wm. J. O'Leary
 Tonnage 340 Built at W. Shields When built 1864
 By whom built Richard & Co Owners Thompson & Co
 Port belonging to W. Shields Destined Voyage Malta
 Surveyed Afloat or in Dry Dock Wm. J. O'Leary

Last Survey, No. 5174 Port of Newcastle Classed B 1
11, 66.

The present Condition of the

Decks	Treeails <u>Shields</u>	Windlass and Capstan <u>Complete & good</u>
Waterways	Breasthooks and Stemson	Pumps <u>do</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>do</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails <u>do</u>
Planksheers <u>good</u>	Keelsons <u>good</u>	Anchors No. of <u>3 1/2, 1 1/2, & 1 1/2</u>
Sheerstrakes	Clamps and Shelves	Cables <u>Said to be Complete</u>
Topsides <u>Plating</u>	Ceiling	Hawsers and Warps <u>Complete & good</u>
Wales	Rudder	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Hand done. Repaired the bottom with Lime and
Subsides anti-fouling paint and one coat of Tallow.
It was in good and efficient condition, and eligible to

Committee's Minute 21st January 1868 Continue as Advised.

Character assigned B 1

Certificate (if required).