

W.E. 2

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 11222		Date of Writing Report	30 th Dec th 1891	Port of Glasgow	(Received at London Office)	THURS. 14 JAN 1892
No. in Reg. Book	Survey held at Glasgow			Date, first Surveyed	Last Surveyed	25 th Dec th 1891
562	on the Machinery of the S.S. "City of Agra"			Master Surveyor	No. of Visits	1
Tonnage	Gross 744	Vessel built at Glasgow	By whom C. Connell & Sons	When 1891-5	YEAR. MONT.	
Net	2133	Engines made at Glasgow	When 1891	Boilers, when made (Main) 1891 (Donkey) 1891		
Registered Horse Power	375	Owners G. Smith & Sons	Port Glasgow	Voyage Indian		
No. of Main Boilers	Two	If Surveyed. Heat or in Dry Dock Govan		Class of Vessel & Machinery	100A1	
Steam Pressure— in Main Boilers	✓	(State name of Dock.)		(As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.)		
in Donkey Boiler	✓				1890	1891
Last Survey No.		Port			562	288

Particulars of Examination and Repairs (if any) Dockings X L.M.C. 6-91 X N.E.B. 6-91

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from

Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do.

Donkey

No

No

No survey due

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Examined all sea-cocks & connections, also propeller and fastenings, and found them in good order.

General Observations, Opinion, and Recommendation:— This vessel's machinery, as far as seen, appears to be in good condition, and in my opinion is eligible to remain as classed without fresh record of survey.

Office or Registration Fee (per Sec. 27)	£ 1	Fees applied for	
Survey Fee (per Section 28)	£ 1	10	
Special Damage Fee (per Section 28)	£ 1		
Travelling Expenses (if chargeable)	£ 1	Received by me,	18

* State if Certificate is required.

Committee's Minute

FRI 15 JAN 1892

Assigned

As per

R. J. Brewster
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.
Glasgow

Insert character of ship and machinery given up in the Register Book

Certificate to be sent to

Treasurer

(The Surveyors are required not to write on or about this page)

L.R.P.H.-Form No. 1

N.B.—If this Report is copied by a printing Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

11222 gles

M.A.
14-1-92

LR-FAF-TB3-117

*OBS APP REQUESTED NOT TO WRITE ACROSS *