

ANNUAL SURVEYS.

43071
FRIDAY 5 OCT 1883

No. Survey held at London Date, first Survey 15 Sept Last Survey 4 Oct 1883

No. in Reg. Book 33 on the S S Aberdeen Master C Matheson (No. of Visits)

Tonnage Net 2371 Built at Glasgow When built 1881 Year. Month. 12

Under Dk. 2565 By whom built R Napier & Co Owners G Thompson & Co

Port belonging to Aberdeen Destined Voyage Australia

If Surveyed Afloat or in Dry Dock Afloat by S S 2 afloat (State Name of Dock.)

Last Survey, No. 42328 Port of London Classed 100 Years assigned. 3. 83. Character in Register Book.

Present Condition of the		Treenails		Years assigned.		Character in Register Book.	
Decks		Breasthooks and Stemson					
Waterways	1	Transoms, Pointers, and Crutches	1	Windlass and Capstan	1		
Comings	1	Timbers of the Frame at the Openings	1	Pumps	1		
Upper Deck Beams & Fastenings	1	Ditto ditto at other places	1	Boats	1		
Lower Deck Beams & Fastenings	1	Keelsons	1	Masts, Yards, &c.	1		
Planksheers	1	Clamps and Shelves	1	Condition, how ascertained	1		
Sheerstrakes	1	Ceiling	1	Sails	1		
Topsides	1	Rudder	1	Anchors, No. of 4 Nos. 11 & 12	1		
Wales	1	Copper or Y.M. Gouther When put on now	1	Cables Part on 11	1		
Plank (Bottom) and Counter	1	Caulking of	1	Hawsers and Warps	1		
Engine Room Skylights	1	Bottom, Deck, & Waterways	1	Standing and Running Rigging	1		
Coal Bunkers, Openings, Lids, &c.	1	Scuppers	1	Cargo and Main Hatchways	1	Hatches 1	
General Observations, Opinion as to Class, &c.							

Bottom be water
She is now in an efficient state and
eligible to remain as before

TUESDAY 23 OCT 1883 18

Committee's Minute

Character assigned

TRW 100A

Senhouse Mastenhead

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book on the Master (No. of Visits)

Tonnage Net Built at When built Year. Month.

Under Dk. By whom built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the									
Decks		Treenails							
Waterways		Breasthooks and Stemson						Windlass and Capstan	
Comings		Transoms, Pointers, and Crutches						Pumps	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings						Boats	
Lower Deck Beams & Fastenings		Ditto ditto at other places						Masts, Yards, &c.	
Planksheers		Keelsons						Condition, how ascertained	
Sheerstrakes		Clamps and Shelves						Sails	
Topsides		Ceiling						Anchors, No. of	
Wales		Rudder						Cables	
Plank (Bottom) and Counter		Copper or Y.M.		When put on				Hawsers and Warps	
		Caulking of						Standing and Running Rigging	
		Bottom, Deck, & Waterways							
Engine Room Skylights	Coal Bunkers, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches					
General Observations, Opinion as to Class, &c.									

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-20/4/82.)
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

ANNUAL SURVEYS.

Number

No. in the Reg. Book

Survey held at

Date, first Survey

Last Survey

18

Master

When built

Owner

Destined for

Port of

Last Survey, No.

Present Condition of the

Deck

Waterways

Compass

Upper Deck Beam & Ribs

Lower Deck Beam & Ribs

Plankings

Sheerboards

Trunks

Wales

Plank (Bottom) and Gunter

Upper Deck Beam & Ribs

Lower Deck Beam & Ribs

General Observations, Opinion as to Class, &c.

Committee's Minute

Character assigned

Director to Lloyd's Register of British and Foreign Shipping

Certificate (if required, to be sent to the Registrar)

18

No. in the Reg. Book

Survey held at

Date, first Survey

Last Survey

18

Master

When built

Owner

Destined for

Port of

Last Survey, No.

Present Condition of the

Deck

Waterways

Compass

Upper Deck Beam & Ribs

Lower Deck Beam & Ribs

Plankings

Sheerboards

Trunks

Wales

Plank (Bottom) and Gunter

Upper Deck Beam & Ribs

Lower Deck Beam & Ribs

General Observations, Opinion as to Class, &c.

Committee's Minute

Character assigned

Director to Lloyd's Register of British and Foreign Shipping

Certificate (if required, to be sent to the Registrar)

18