

1.

Sent to Chief Surveyors 30.8.04

Received from Chief Surveyors _____

VESSEL'S NAME St. S. S. "Emerald" Report Sub. No. 14028

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When done _____

± 100 A 1 ("Steel")

1 DR (SC) "Well back"

H.B = Cell DB a 57' f 59' 1700 FPT 750 APT 100

BK 7" 3BH Am. Lloyd's A9 CP Q103' B11 F32' Melby Aff.

C.H. J.
30/8/04



© 2018

Lloyd's Register
Foundation