

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S.S. "FULLAGAR"*

Report

Lw.

No. 81095.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case. The Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.12.

Nature of Survey

When due

✱ 100 A.1. (steel) "Electrically welded"
 "Subject to Annual Survey"
 "Experimental."

1 Dk (steel) "Well Dk."

DB 14' 2 1/2". FPT 54". APT 18".

FK. 3 BH. Conn. Lloyd's AYCP Q 88', B 9', F 26'.

Machy aft.



© 2018

Lloyd's Register
Foundation