

Report to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel S.S. "Fezara"*

Report *Glo.*

No. *42784*

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. -- Extract from Sub-Committee's Report 24592.)

Nature of Survey *First Entry.*

When due _____

**- 100 A. I. (Steel).*

2 Dks (Stl. U. teak-s) 3rd Dk (Stl) in Nos. 1 + 2 Holds.

Cell D. B. 340', 953 t. FPT 69 t, APT 138 t.

FK, 7 BH, pt. Cem, Lloyds A. & C. P 46', B 154', F 46'.

[Handwritten signature]

aw. l.
© 2018

21/2/23.



Lloyd's Register
Foundation