

N.N. "DAVARR ISLAND"

141
F.E.
RET

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl Se CAPE KANIN Rpt. Jul No. 40993

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No. 1960

Depth "d" _____

Framing: Table No. _____

Description angle frames as approved

2nd Longitudinal No. 5372

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 10

~~Deck~~ Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel). Steam Hawker.

10^K

B.K 7¹/₂, H.B.H. 1 cm Clayds A CP.

Q 7¹/₂, F 22¹/₂.



© 2019
Lloyd's Register
Foundation