

## Lloyd's Register of Shipping.

(Report on Vessel No. 40993. Port Hull)No. \_\_\_\_\_ SHIP FORGINGS ~~OR~~ CASTINGS.

I have to report that the undermentioned Iron ~~or~~ Steel Forgings or Castings, manufactured by T. S. Forster & Son Ltd. of Sunderland for the Vessel No. 1083, being built by Messrs. Becham & Son Ltd. of Selly have been inspected by me as set forth below and found to be, so far as can be seen, Sound

Mark on Forgings or Castings.

Lloyd's

No. 58384810.5.30J. Dale  
Sunderland

STERN FRAME.

RUDDER FRAME.

STEM.

Material\* ...

How made ...

If annealed ...

Dimensions ...

Progress on Inspection ...

Date when Inspected ...

## CASTINGS.

Tests on Standard Test Pieces.

## Tensile Test—

Tons per square inch ...

Extension per cent. ...

## Cold Bending Test—

Angle before fracture ...

## Drop Test—



Height from ground ...

## Hammering Test—

If made according to Rules and found satisfactory ...

Scrap iron  
Forged & Smithed.5 1/2 dia 5 3/2 x 3  
Forging & Smithing  
10.5.30

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



Fee (if any chargeable) £ : :

To be paid at

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.