

Present to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

Stat S.S. "CARPIO"

Report

Riv

No. 82891

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry

When due _____

✱ 100-A-1. (Steel) "Shelter Deck with foreboard"

1 Dk (Steel) ✓ Shelter Dk (Steel)

Cell 11B 222' 444', FPT 63', APT 18'

FK, Collision BH to Shelter Dk, 3BH to Upper Dk, Cam, Plyds A, CP.

Date of build 8.21



© 2019

Lloyd's Register
Foundation

Handwritten initials: JH

Handwritten date: 27.10.21