

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____ 74

NAME *Shells "Elluvia"*

Rpt. *Amo* No. *73*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

verse No. *56-08*

Depth "d" *15.95*

ing: Table No. *2*

Description *Frame & reversed frame*

itudinal No. *13/80*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{12.85}{9.17}$

dge Deck Sheerstrake *as approved*

See Endorsements re Equipment.

This vessel appears to have been built in accordance with the
s and the approved plans, and it is submitted she is eligible to

lassed *100 A - (Steel)*

1 DK (Steel)

Cell 8B 196' 364L FPT 44L APT 59L

FK. 4BH. Cam. P17. B 63' F 25'

M
16-6-19

b



© 2020

Lloyd's Register
Foundation

00013-002023-0167