

1

Tulford

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stat S.S. "AGWIMEX" Report Phl No. 4243**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____ When due _____

✱ 100. A-1. (Shel) 'Shelter Deck with freeboard

"Camping petroleum in bulk"

1 Dk (Shel) ✓ Shelter Dk (Shel) ✓ Helppanes longitudinal framing

Cell Dk. u E.B 84' f 40' 448t, FPT 186t APT 84t

FK, 18 BH (9 BH to Shelter Dk, 9 to upper Dk) pt Cen, A. CP.

F 414 on Shelter Dk, Mchly app



© 2020

Lloyd's Register
Foundation

A handwritten signature in dark ink, possibly 'M' or 'H'.

2-11-21

002051-002061-0095