

Hansa

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME S/S K "CORDELA"

Rpt.

Jul

No. 41216

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02).

P. Lang

Transverse No.

1995

Depth "d"

12.83

Framing: Table No.

Description

angle frames as approved

2nd

Longitudinal No.

5477

Proportions

Length
Depth =

9.82

Deck Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.I. (Steel). Steam Trawler.

1 D¹⁰

B.K 7½, H.B.H, Cmw, Lloyds A/RP.

Q 78', F 19'.



© 2020

Lloyd's Register Foundation

002051-002061-0166

20/9/30