

EX Welsh Rose

N.N.

"SUSSEX BIRCH"

1m, 8, 21.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S/S "BROOKSIDE"

Rpt. Hul.

No. 33811

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 39.87

Depth "d" 10.5

Framing: Table No. 3

Description Single angles and bulb angles.

Longitudinal No. 6977

Proportions Length = 13.46
Depth =

~~Both~~ Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed X 100 A1 (Steel)

1 Dk. (Steel) Well dk.

Cell D.B. f 105 118t. FIT 43t. AIT 25t.

FK 3 BH. Cem. Lloyds A & CP Q 99' B11' F 24. Mchly apl.

6-11-22



© 2020

Lloyd's Register
Foundation

002062-002070-0265