

1.

Now Lynntown Immo Ragnar

Sent to Chief Surveyors 16. 6. 03

Received from Chief Surveyors

VESSEL'S NAME S.S. "Hermia" Report Genk No. 13645

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First entry When due

+ 100 A 1 ("Steel")

1 BR (Sec) + deep framing.

N. B = Cell DB a 86' a E 4 B 32' f 126' 556t APT 27t

FK 5BH Cen. Doyli A 4 CP P 29' B 81' F 32'

C.H.P.
16/6/03

The Surveyors should be requested to state whether the main deck beams have been fitted as approved, or particulars of their nature have been omitted from their report.

C.H.P.

Del. n. 17/6/03



© 2020

Lloyd's Register
Foundation

002094-002100-0199