

2m, 8, 19.

002101-002108-0243

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "SAINT BARCHAN". Report Gls. No. 39313

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey _____ When due _____

❖ 100 A.1. (Steel).

1 Dk. (Steel). "Well Dk.")

FPT 31t. APT 12t.


BK 7', 3 BH. Cem. Lloyd's A. & C.P. Q81', B8', F24',

Machinery aft.

by 22/11/91

see letter

The Surveyors should state the size of keel and stem.



© 2020

Lloyd's Register
Foundation

14. 11. 19.