

9.25.

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

*MT SS Gorilla*

Report

*JS*

No.

*44736*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.10.42.)

Signature of Surveyor

*Alterations*

*701*

When due

*2.26*

*1 SK (SK) & Shellies dk (p. 511)  
3 BH Collision BH to Shellies deck*

*The class of this vessel has been amended  
by the Glasgow Committee to 100 A.1  
Shellies OK with put?*

*Side - Cargo battens not fitted.*

*It is concluded that the collision bulkhead has  
been explained to the uppermost deck as shown on  
the approved plan of alterations, but the Surveyor should  
state if this is so*

*W.S. M.A. 12.6.25*

002127-002137-0115

