

No. in Survey held at Hull. Date, First Survey 29 Aug 29 Last Survey 29
Reg. Book. 10810 on the Steam Trawler "DINAMAR" (Number of Visits 29)
Built at Leby. By whom built Cochrane & Sons LS Yard No. 1671.

pt. 7.

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 10

Lloyd's Register of Shipping.

(Report on Machinery, No. 40685 Port Hull)

No. 18729 ENGINE FORGINGS OR CASTINGS.

I have to report that the ~~Forgings or Castings~~, as herein described, manufactured by The Rotherham Forge & R. Mills Ltd. of Rotherham for the Engines No. 598 being constructed by Messrs Amor & Smith Ltd. of Hull for the Ship No. _____, being built by _____ of _____

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to _____

on Forgings or Castings

Lloyd's

No. 2307

R.W.F. 4/9/29



R.W. Fawcett

Sheffield
7/9/29

	CRANK SHAFT.	THRUST SHAFT.	INTERMEDIATE SHAFT.	TUBE SHAFT.
	<u>1 Bar.</u>			
	<u>FLYWHEEL SHAFT.</u>			<u>SCREW SHAFT.</u>
Material	<u>Summit Steel</u>			
Made	<u>Forged</u>			
Heat-treated	<u>Yes</u>			
Dimensions, Forgings	<u>Dia 7 3/16"</u>			
Material, Castings	<u>Black Forging</u>			
Test on Specimen	<u>965</u>			
Test on Standard Test Pieces	<u>30-8</u>			
Test per square inch	<u>33.0</u>			
Elongation per cent	<u>180.</u>			
Bending Test—				
Time before fracture				
When Inspected	<u>28/8/29 to 4/9/29</u>			

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

(if any chargeable) £ ✓

To be paid at ✓

If of wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.

002138-002150-0167

Lloyd's Register
Foundation