

Nicolau Maria

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl S "OILSHIPPER" Rpt. Inc No. 81622

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

^{1st Long} Transverse No. 12742 Depth "d" 20'

Framing: Table No. ✓ Description Longitudinal framing

^{2nd} Longitudinal No. 34575

Proportions Length 13.19
Depth =

Deck Sheerstrake as approved

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A. I. (Steel) "Carrying Petroleum in Bulk"
2 D^o (Stl). Web Frames, Longitudinal Framing.
Cell D.B. & E. B. 62' 18" bt, D.T. & 30' 1225, F.P.T. 776, A.P.T. 2085
F.K., 15 B.H (10 B.H to upper str, 5 B.H to 2nd D^o) pt Cen, Clyde Arcep
P 106', B 26', F 39'. Machinery aft.

[Signature]
8.8.27



© 2020 Lloyd's Register Foundation

002194-002205-0090