

FREEBOARD VERIFICATION FORM FOR TANKERS.

When received in London Office

Port

Rotterdam

Name

"Helix"

Official No. 162562 Signal Letters

No. in Reg. Book

Port of Registry

London

Gross Tonnage

3007

Class

Date of Verification

Name of Owners

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE,
~~WOOD~~/STEEL *after* DECK.FROM CENTRE OF
DISC.

Tropical Fresh Water	1 ft. 0 ins.	9 1/4 ins. above
Fresh Water	1 ft. 4 1/2 ins.	4 3/4 ins. above
Tropical	1 ft. 4 3/4 ins.	4 1/2 ins. above
Summer	1 ft. 9 1/4 ins.	
Winter	2 ft. 1 3/4 ins.	4 1/2 ins. below
Winter North Atlantic	2 ft. 4 3/4 ins.	7 1/2 ins. below

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:—

Surveyor

(To be filled up in London Office.)

Date of Committee's Minute

Particulars for Record
in Register Book.

Moulded Depth	ft.	28 1/2 ins.
Freeboard	ft.	ins.
Corresponding Draught	ft.	ins.

Freeboards compared and found correct by

Date

Form for Certificate

L. L. 2 -

30/4/40

Certificate written

28 OCT 1938

Noted for posting

2m, 12, 38.

Closing applications as before

002206-002214-0211

© 2020

Lloyd's Register
Foundation