

F.E.

Received by Chief Ship Surveyor 14.8.18

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheels Kent

Rpt.

111

No. 7177

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 92.25

Depth "d" 15.72

Framing: Table No. 3.

Description Bulb angle as approved

Longitudinal No. 42435

Proportions Length = 10.05
Depth =

Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed \clubsuit 100 A-1 (Steel) Shelter Deck with freeboard," as recommended. The Summer freeboard of 9.0 from centre of disc top of statutory deck line at Shelter deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, shown on the accompanying verification form to be inserted in the certificate of classification.


2 Dks (Steel) & Shelter DK (Steel)

Call D.B. 382 14036. D.T. 23 1706 F.P.T. 1286 A.P.T. 326

F.K. Collision 134 1/2 Can. Leg. 2000. B 275 F 49' a Shelter DK

Date of Build 6.18.

002260-002268-0020



© 2020

Lloyd's Register
Foundation