

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl S^m MACUBA*

Rpt. *RA* No. *20458*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st Long

Transverse No. *15300*

Depth "d"

Framing: Table No. *✓*

Description *Transverse framing at sides
Longitudinal framing at bottom and deck*

2nd Longitudinal No. *43087*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.24}{.}$

Deck Sheerstrake *as approved*



Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*✠ 100 A. I. (Steel). Carrying Petroleum in Bulk
1st D⁺ (Stl), 2nd D⁺ (Stl) clear of cargo tanks.
Longitudinal framing at bottom and at deck
Cell D.B.H.E 69' 222t, D.T.f 32' 355t, F.P.T. 225t, A.P.T. 415.
F.K, 14 B.H, Clyds A.C.P.
P 103', B 35', F 43'.
Machy apr.*

[Signature]
17.7.31

002269-002278-0044 © 2021

