

1

(5)

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME *Stl T. S. S. Dredger*

"No 35"

Report *Link*No. *18437***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey \_\_\_\_\_

*1st Entry*

When due \_\_\_\_\_


+ 100 A.I. (Steel) "Hopper Dredger"

1 dk (lth - bt ws.)

D.T. 9' 486.

F.K. 5 B.H. Cmw, Lloyds Ar CP. machy aft

*P. 1*  
6.8.25



© 2020

00279-00288-001

Lloyd's Register  
Foundation