

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

(Report on Vessel No. 44467 Port Hull)

W. Kingston Andaleuco

No.

SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~
Castings, manufactured by Messrs E Gopling & Son Ltd
of Sunderland for the Vessel No. 584, being built
by Messrs Cook Weller & Gamble of Beverly
have been inspected by me as set forth below and found to be, so far as can
be seen, Sound

~~Forgings or Castings.~~

Lloyd's

No. 7991

20.12.33

J Dale
Lower plate & gudgeon Sunderland

STERN FRAME. to Deck RUDDER FRAME.

STEM.

al* ...
ade ...
aled ...
ions ...
s on Inspection ...
hen Inspected ...
CASTINGS.
on Standard Test
Pieces.
Test—
per square inch ...
nsion per cent. ...
ending Test—
e before fracture ...
est—
at from ground ...
ring Test—
ade according to Rules ...
d found satisfactory ...

Cast steel
Electric furnace
yes
pattern
Cleaning & testing
20.12.33

35.5-

28%

120

Hammered.


SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(if any chargeable) £ ✓

To be paid at

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

T.



© 2020

Lloyd's Register
Foundation

00279-00278-018