

## REPORT ON ELECTRIC LIGHTING INSTALLATION. No.

Port of Hartlepool Date of First Survey 3.5.21 Date of Last Survey 28.10.21 No. of Visits 7  
 No. in on the Iron or Steel S. S. "Lanciana" Port belonging to Liverpool  
 Reg. Book Built at Hartlepool By whom Messrs Irvine's Shipbuilders When built 1921  
 Owners Messrs Furness Withy & Co. Owners' Address Royal Liver Bldg., Liverpool.  
 Yard No. 586 Electric Light Installation fitted by Messrs Campbell & Jekewood Ltd. When fitted 1921

## DESCRIPTION OF DYNAMO, ENGINE, ETC.

Two Campbell & Jekewood 4 pole Compound Wound Dynamos, 100 Volts 20 K.W. and 100 Volts 7½ K.W. driven by "Howard" enclosed Engines.

Capacity of Dynamo 1:200 & 1:75 Amperes at 100 Volts, whether continuous or alternating current Continuous

Where is Dynamo fixed In Access of Engine Room Whether single or double wire system is used Double.

Position of Main Switch Board Alongside Dynamos having switches to groups A.B.C.D.E.F. of lights, &c., as below

Positions of auxiliary switch boards and numbers of switches on each A. Chart Room (8) Saloon Pantry (10) Engineer's Alleyway (6) A/S (6) B. Engine Room (2) Forward Mast House (4) Main Mast House (4) C. Engine Room (8) Boiler Room (6)

If cut outs are fitted on main switch board to the cables of main circuit Yes and on each auxiliary switch board to the cables of auxiliary

circuits Yes and at each position where a cable is branched or reduced in size Yes and to each lamp circuit Yes

If vessel is wired on the double wire system are cut outs fitted to both flow and return wires or cables of all circuits including lamp circuits Yes

Are the cut outs of non-oxidizable metal Yes and constructed to fuse at an excess of 50% per cent over the normal current

Are all cut outs fitted in easily accessible positions Yes Are the fuses of standard dimensions Yes If wire fuses are used

are permanent instructions fitted on or near each switch board giving particulars of proper size of fuse for each circuit Yes

Are all switches and cut-outs constructed of incombustible materials and fitted on incombustible bases Yes

Total number of lights provided for 258 arranged in the following groups:—

A Accommodation & Navigation 175 lights each of 4-16 & 32 candle power requiring a total current of 75 Amperes

B Bargo 12 lights each of 300 candle power requiring a total current of 36 Amperes

C Machinery Spaces 45 lights each of 16 candle power requiring a total current of 51 Amperes

D Ash House 1 lights each of — candle power requiring a total current of 40 Amperes

E Ash House 2 lights each of — candle power requiring a total current of 40 Amperes

F Forward Mast 2 Mast head light with 2 lamps each of 32 candle power requiring a total current of 2 Amperes

2 Side light with 2 lamps each of 32 candle power requiring a total current of 2 Amperes

12 Cargo lights of Each 600 candle power, whether incandescent or are lights Incandescent

If arc lights, what protection is provided against fire, sparks, &c. None Fitted

Where are the switches controlling the masthead and side lights placed In Chart Room.

## DESCRIPTION OF CABLES.

Main cable carrying 200 Amperes, comprised of 19 wires, each 15 L.S.G. diameter, .0765 square inches total sectional area

Branch cables carrying 56 Amperes, comprised of 7 wires, each 15 L.S.G. diameter, .0282 square inches total sectional area

Branch cables carrying 40 Amperes, comprised of 7 wires, each 16 L.S.G. diameter, .02227 square inches total sectional area

Leads to lamps carrying 3 Amperes, comprised of 3 wires, each 20 L.S.G. diameter, .003 square inches total sectional area

Cargo light cables carrying 1.5 Amperes, comprised of 12 wires, each 30 L.S.G. diameter, .0015 square inches total sectional area

## DESCRIPTION OF INSULATION, PROTECTION, ETC.

Pure and Vulcanised Rubber and Rubber Tape, the whole vulcanised together and lead sheathed or wire armoured, or lead sheathed and wire armoured and Braided.

Joints in cables, how made, insulated, and protected Done except Mechanical.

Are all the joints of cables thoroughly soldered, resin only having been used as a flux — Are all joints in accessible positions, none being made in bunkers, cargo spaces, or spaces which may at any time be used for carrying cargo, stores, or baggage

Are there any joints in or branches from the cable leading from dynamo to main switch board Do.

How are the cables led through the ship, and how protected Lead sheathed armoured & braided clipped to under side of Decks, or Bulkheads. Lead sheathed cables clipped in Saloon Cabins.



© 2020

Lloyd's Register Foundation

002274-002288-0158

DESCRIPTION OF INSULATION, PROTECTION, ETC.—continued.

Are they in places always accessible

Yes.

What special protection has been provided for the cables in open alleyways or where exposed to weather or moisture

Cables enclosed in Galvanised Iron Pipes.

What special protection has been provided for the cables near galleys or oil lamps or other sources of heat

Lead covered, Armoured Braided Cables

What special protection has been provided for the cables near boiler casings

As above.

What special protection has been provided for the cables in engine room

Do.

How are cables carried through beams

Through holes bushed with lead through bulkhead, &c. W.T. Glands.

How are cables carried through decks

Through Galvanised Iron or Brass Tubes.

Are any cables run through coal bunkers

Yes or cargo spaces

Yes

or spaces which may be used for carrying cargo, stores, or baggage

Yes

If so, how are they protected

Lead covered and Steel wire Armoured cables.

Are any lamps fitted in coal bunkers or spaces which may at times be used for cargo, coals, or baggage

Do.

If so, how are the lamp fittings and cable terminals specially protected

Where are the main switches and cut outs for these lights fitted

If in the spaces, how are they specially protected

Are any switches or cut outs fitted in bunkers

Do.

Cargo light cables, whether portable or permanently fixed

Portable

How fixed

In vessels fitted on the single wire system, how is the dynamo terminal fixed to the hull of vessel

How are the returns from the lamps connected to the hull

Are all the joints with the hull in accessible positions

The installation is

Yes

supplied with a voltmeter and

Yes

an amperemeter, fixed

on Main Board

VESSELS BUILT FOR CARRYING PETROLEUM.

In vessels built for carrying petroleum, are all switches and cut-outs fitted in positions not liable to the accumulation of petroleum vapour or gas

Are any switches, cut outs, or joints of cables fitted in the pump room or companion

How are the lamps specially protected in places liable to the accumulation of vapour or gas

The copper used is guaranteed to have a conductivity of 100 per cent. that of pure copper.

Insulation of cables is guaranteed to have a resistance of not less than 2500 megohms per statute mile after 24 hours' immersion in seawater.

The foregoing statements are a correct description of the Electric Light installation fitted by us on this vessel and we declare that it is at this date in good order and safe working condition.

CAMPBELL & ISHERWOOD LTD.

P. O'Niscoll

Electrical Engineers

Date 15<sup>th</sup> Nov. 1921.

COMPASSES.

Distance between dynamo or electric motors and standard compass

About 150 ft.

Distance between dynamo or electric motors and steering compass

" "

The nearest cables to the compasses are as follows:—

A cable carrying 9 Amperes 10 feet from standard compass 10 feet from steering compass

A cable carrying 20 Amperes 50 feet from standard compass 50 feet from steering compass

A cable carrying Amperes feet from standard compass feet from steering compass

Have the compasses been adjusted with and without the electric installation at work at full power

Yes

The maximum deviation due to electric currents, etc., was found to be

no

degrees on

any

course in the case of the

standard compass and

no

degrees on

any

course in the case of the steering compass.

FOR IRVINE'S SHIP BUILDING & DRY DOCKS CO. LIMITED

Builder's Signature.

Date

November 21/21

GENERAL REMARKS.

Managing Director

This installation has been fitted under survey. The materials and workmanship are good. On completion it was found satisfactory under full working conditions.

Fee £21.10.0

Applied for 22/11/21.

Paid.

Electric Light.

R. D. Shilston

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.