

s/s "Scillonian"

Gls 45332.

It is submitted that the Falmouth
Surveyors be requested by wire to state
whether the bilge suction in No 2 hold
has been fitted as required & advised by
the Glasgow Surveyors.

W.D.
4/2/26

© 2021

Lloyd's Register
Foundation

002298-002304-0123