

Do. of
and
Total
Do. of
Do. of
Do. of
Do. of
Do. of
Do. of
Do. of
Do. of

15c, 1, 14.

1

Sent to Chief Surveyors

27. 5. 14

Received from Chief Surveyors

VESSEL'S NAME

St. S. Rother

Report

JH

No.

16681

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Int

When due

1- 100 A.1 (Stub)

1 SH (M)


M. B. Cell DBa 51' E 13' F 92' 197' F 13' A 17' 28'

JH. 5 BH. 'Cm.' Lays a 16' P 38' B 88' F 37'

M. W. 5. 14

002330-002339-0005

© 2020



Lloyd's Register
Foundation