

3m. 4. 21.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. BROUGHTY Report Bel No. 8555
8540

For the CHIEF SHIP SURVEYOR ~~and~~ CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey _____ When due _____

Survey Completed at Glasgow

✕ 100-A-1. (Steel)

1 Dk. (Steel) "Well Deck"

Cell IB f 97' 104t, FPT 36t, APT 2t

FK, 3BH, Cem, Ploys A. & P, Q96' B11' F23' Melby Off

M

JD

28-10-21



© 2020

Lloyd's Register
Foundation

002340-2351-0016