

No. and size:—In Machinery Spaces

, &c. Pump room 10" 2 $\frac{1}{2}$; deep tank 30' 2 $\frac{1}{2}$ " Two 4' 0" "V" cofferdam 40' 3" 2 $\frac{1}{2}$ "

endent Power Pump Direct Suctions to the Engine Room Bilges, No. and size

Twin 1 x 4 $\frac{1}{2}$ " and 1 x 6 $\frac{1}{2}$ " V

ge Suctions in

mpv. "Elax."

Ams 10816.

3rd ✓

low the deep w
d brass coverin

It is submitted that
this vessel is eligible for
THE RECORD. + LMC 10. 27. CL.

Oil Engines 4SC.DA. 1204 NH.
6 Cy. 32 $\frac{1}{4}$ " - 59." 2DB. 180 t_b.

J.W.D.
4/11/27.
LR

© 2020

002374-002384-0124

Lloyd's Register
Foundation

7/4/20

ECEIVERS:—Is each receiver, which can be isolated, fitted with a safety valve as per Rule

ternal surfaces of the receivers be examined

Ye ✓

What means are provided for cleaning their inner surfaces

man

Each arrangement fitted at the lowest part of each receiver

Ye ✓