

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME Steel S.S. "EIGEN HULP Vll" Rpt. Rot. No. 10773

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 59.83 Depth "d" 17.83

Drawing: Table No. 3 page 10. Description Bulb angle

Longitudinal No. 16154

Proportions $\frac{\text{Length}}{\text{Depth}} = \underline{12.96}$

Upper Deck Sheerstrake as approved.


See separate endorsement re secondhand material used.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A.1. (Steel), as recommended.

1 Dk. (Steel).

Cell DB 225' 481t. APT 40t.

FK. 4 BH. Cem. A.& C.P. P24', B65', F27'.


7. 5. 19.