

4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

26 SEP 1957

NAME.....BADARPUR.....REPORT.....Krh.....No. 2666

The propeller and some machinery parts examined with vessel afloat after grounding.

The Surveyor recommends that the propeller and fastenings be specially examined at the next drydocking.

IT IS SUBMITTED this vessel is eligible to remain as classed, subject as recommended.

*Sub*  
20.9.57.



© 2020

Lloyd's Register  
Foundation

002485-002489-0104