

1

Row "Aradryfe"

Sent to Chief Surveyors .....

Received from Chief Surveyors .....

VESSEL'S NAME

Shells St. Dunstons Shlb

Report

No. 37572

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/2.)

Nature of Survey .....

When due .....

✱ 100A-1 (Steel)

10K (Steel) Weld on

Cell D.B. + 126 1866 F.P.T. 666 A.P.T. 486

E.K. 3BH Cam. Logdared Q 139 F 23

M  
21-3-18

The Surveyors should be informed the approved plan of strengthening of the bottom found should be forwarded with the 1<sup>st</sup> entry report of the sister vessel.



© 2021

Lloyd's Register Foundation

002529-002535-0221

in Engine and Boiler space  
Remainder in Holds.....  
QUARTER  
BEAMS, Upper Deck, Single Angle, Bulb

5 3 .34 5 3 .34

Tie Plates, outside Hatchways.....  
Deck.\* Material and thickness