

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

S.S. "Beryl"

Report

Gh

No. 44173

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

1st Entry.

When due _____

+ 100 A1 (Steel)

1 Dk. (steel)

"Well deck"

F.P.T. 60 T. A.P.T. 6 T.

BK. 7.3 B.H. com. Lloyds A. & C.P. D. 94' B. 9' F. 27' "Machinery aft."

The Certificate of Classification, to be endorsed
"No alterations not fitted," and the same
notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation

R.M.
20/11/34

002568-002576-0101