

The class is subject to the starboard main engine No.3  
cylinder jacket and the cylinder covers of the port centre  
and port after diesel generators being examined by 4.59,  
also to the after end of the port sternbush being specially  
examined at the next TS.

4E

27 OCT 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....  
CLYDEBANK Fre 1482  
SHIP'S NAME.....REPORT.....No.....

The Surveyor Reports No.5 port cylinder cover  
defective and spare cover now fitted.

IT IS SUBMITTED this vessel is eligible to  
remain as classed subject as above.



© 2020

24.10.58

Lloyd's Register  
Foundation

0026159-002646-0309