

15c, 1.14.

1

Sent to Chief Surveyors 25. 2. 14

Received from Chief Surveyors

VESSEL'S NAME *Shells "Carrowdore"* Report *Sl* No. 33658

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

1st Enly -

When due

100A-1. (Steel)

1 Dr (pl. steel). well Dr

WTB = cell 2 B f 103' 16 2/3 E. FPT 48 E APT 6 E

BK 7 1/4. 3 BK. Cen. Lys ar. Q. 103' 13 9/16 F 33' Enly abl.

M
25. 2. 14.

It is concluded the particulars of the meeting of the hulls of I strake as given in the report are intended to apply to the sheer or B strake of plating, & that the hulls of the former strake are triple overlapped for 1/2 L amidships but the Surveyors should state if this is so.

Lt. W. G. L. :-

M
25. 3. 14

M
25. 2. 14



© 2020

Lloyd's Register Foundation

002667-002673-0124

Angles on upper edge

Deck.* Material and thickness