

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *S.S. "PAN BOLIVAR"* Rpt. *NWC* No. *87354*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92).

1st Long
Transverse No. *17267*

Depth "d"

Framing: Table No.

Description *Longitudinal framing*

2nd Longitudinal No. *48783*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13}{14}$

Deck Sheerstrake

as approved.

Revised Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*✠ 100 A1. (Steel). Carrying Petroleum in Bulk.
2 D^{ks} (Stl) & Web Frames. Longitudinal framing.
All DB u E&B 83' 265t, DTf 45' 623t, FPT 227t, APT 184t.
FK. 16 BH (12 BH to upper D^k, 4 BH to 2nd D^k), pt Cen, Lloyd's A&CP.
P 117' B 42' F 50'.
Machy aft.*



© 2020

Lloyd's Register Foundation

Wf
16.7.31.