

Class is subject to

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME.....CORILLA.....REPORT.....Sng.....No. 13725..

CS advanced.

DBS due 3.60. Now held.

Docking.

The Surveyor reports that a new cylinder block now satisfactorily fitted to the windlass.

IT IS SUBMITTED this vessel is eligible to remain as classed, with fresh record of ABS 1.60.

