

2 - JUN 1958

Received from Chief Ship Surveyor

NAME "GAELIC FIDELITY" REPORT Lon. No. 138000

standing Conditions of Class: Subject to Nos. 1 & 2 keel plates and side shell plates J.16 & K.16 (p.s. from fwd) being specially examined and dealt with as necessary by next Special Survey, also to fractured hawse pipe (p & s) being examined and dealt with as necessary next drydocking.

sement of Certificate (~~As before~~ or None)

e of Present Survey: (Afloat ~~and in dry dock~~)

Wear and tear repairs.

Recommendation:

SUBJECT as above, and to repairs to No.6 centre cargo tank and bottom shell plating being effected on arrival at a N.E.Coast port and prior to loading further cargo.

As Now. Subject.

Sold Shipbreakers



© 2021

Lloyd's Register Foundation

James
30/5/58.

002690-002700-0229