

1

Sent to Chief Surveyors 7.1.14

Received from Chief Surveyors

VESSEL'S NAME Steel S. S. "Clarecastle" Report GLs No. 34713

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due

✠ 100 A.I. (Steel)

1 DK (Steel) Will DK.

W.B = Cell DB of 103' 161t F.P.T. 46t A.P.T. 7t.

BK 7¼", 3 B.H. Cam., Lloyds A & C.P., Q 103', B. 9', F 33'
mely aft.

MP A.P.
7.1.15

New Form



© 2020

Lloyd's Register
Foundation

002701-002710-0005

S/S. "Scomber"? the only one today New York



© 2020

Lloyd's Register
Foundation