

4E


ject to

28 MAR 1960

Chief Engineer Surveyor.....
 Received from Chief Engineer Surveyor.....
 NAME..... DAI HATIM.....
 REPORT..... Cbo..... No. 4586.....

The Surveyor reports some repairs effected to the attached main engine lubricating oil pump. Also the Surveyor reports temporary cartridge type element now fitted to the lubricating oil filter, and the Surveyor recommends that the class be made subject to the main engine lubricating oil filter being repaired before the end of March, 1960.

IT IS SUBMITTED this vessel is eligible to remain as classed, subject as recommended.



24.3.60.



© 2020

Lloyd's Register
Foundation

002701-002710-0129