

Surveyed Afloat or in Dry Dock: *QUEENS DOCK*
 Well Deck or DBa _____ feet: *uE & B* _____ feet: *f* _____ feet
 Total capacity _____ tons: *FPT* _____ tons: *APT* _____ tons: *MT* _____ feet _____ tons.

Particulars of Class _____
 precisely as in R _____

CHARACTER:
 Special Survey
 last Survey and of
 official Surveys

COPY.

clip 'M'

LONDON OFFICE.

Your Ref: Repair Dept.

6th February, 1950.

Dear Sirs,

S.S. "LOCH DEE"
Conversion to Oil Burning.

I am favoured with your letter of the 2nd instant, and in reply have the pleasure to inform you that the plan showing details of Oil Fuel Supply Tanks will be approved, provided the welding be carried out to the satisfaction of the Society's Surveyor and the tanks be constructed under the usual conditions of survey and testing.

The copies of the plan have been retained for the use of the local Surveyor and for record purposes in this office.

Yours faithfully,

Secretary to the
 Scottish Committee.

Messrs. Alex. Stephen & Sons Ltd.,
 Linthouse,
 GLASGOW, S.W.1.



© 2020

Lloyd's Register
 Foundation

002711-002716-0198

Condition of Decks	<i>Good.</i>	Bulkheads	<i>In spaces examined - Good</i>	Engine Room Skylights	<i>Good</i>	Other	
	<i>Good</i>	Ceiling	<i>In spaces examined - Good</i>	Coal Bunkers, Openings, Covers, &c.	<i>Good</i>		