

FRAMES, Spacing amidships .....

28

Bracket Floors, Frame .....

6 3/2

5m, 9.35.

1

Sent to Chief Surveyors .....

Received from Chief Surveyors .....

VESSEL'S NAME Steel Screw "JALAYATUNA" Report Gr. No. 20168

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due --

100A1

2 Dks.

Cell. DB 343' 1047t, FPT 78t, APT 47t.

FK, 6 BH, Cem. Lloyd's A &amp; CP.

P 40', B 145', F 32'.

This ship is similar to "JALAGANGA"



© 2020

Lloyd's Register Foundation

002711-002716-0135

Second Deck, amidships, Angle, E or [ .....

8 3

Spacing..... 28

28

1/2 3  
1/2 3  
3/2 3/2

2 1/2

1/2 3/2

4

1 @ 3

7 x 50

2 3/2

6

yFRAME-

yFRAME-

4 3/4

70 x 4

-42

YES

YES

YES

YES

1/2 3

3 3

28

8 3

28