

M/S "CARL SHAMN"

002725-002735-0124

Considered the following machinery items should be opened & examined:-

Scavenge pump

Bilge pump

One lub. oil pump

Pumping arrangements

One air compressor (not Star For?)

One main air receiver

N^o 2 diesel generator engine

Electrical equipment

Fire Extinguishing arrangements.

Port Donkey boiler should be examined in accordance with Circular 2151, of the
which and Adv. date of DBS could be assigned if desired subject to Starboard
Donkey boiler not being used until repaired.
All machinery should be seen under working conditions.

© 2020

Lloyd's Register
Foundation

EWK
24/10/60