

Donkey Boilers made at Looperhagen By whom made AMERICAN PETROLEUM COMPANY Boiler No. 1935
 Brake Horse Power 2 x 2000 Owners SOCIETE ANONYME BELGE Port belonging to Antwerp

Im.11.35.

1E

Received by Chief Engineer Surveyor _____ Received from Chief Engineer Surveyor _____

VESSEL'S NAME Esso Belgein Rpt. Open No. 10125

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engine 2. S. C. S. A
14 Cy. 19 1/16" - 35 7/16"



~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner yes
 If fitted with an outside gland of approved type no

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + Linc. 1. 37

2 O.B. 200 lb. - ~~3/4~~
1 O.B. (Centre) 214 lb.

John
3. 2. 39



© 2021

Lloyd's Register Foundation

002736-002742-0036

compartment to another _____

If a wood vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturating the woodwork _____

Main Air Compressors, No. _____ No. of stages _____ Diameters _____ Stroke _____ Driven by _____