

yes Was Damage Report issued? -- Int. Cert.? attached  
sent Last Report (For Head Office only)  
how

S.S. Cff. (Dr.) - 6-56

S.P.S.

O.F.

4E

26 JAN 1959

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

'S NAME

CHA

REPORT

Rot.

No. 40620

MBS due 1.59 part held now.


Screwshaft examined.

WILL BE

IT ISSUBMITTED that this vessel ~~is~~ eligible  
for the record MBS 12.58 on completion, as this report,  
record TS CL 12.58 now.

EW

22.1.59.



© 2020

002450-002753-0058

Lloyd's Register  
Foundation

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS