

e all the bilge suction pipes fitted with roses *yes*
 e all connections with the sea direct on the skin of the ship *yes*
 e they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates *yes*
 Are the roses in Engine room always accessible *yes*
 Are they Valves or Cocks *both*
 Are the Discharge Pipes above or below the deck *both*
 of and brass

s/s "Tjibesar."

Gls. 42246.

It is submitted the Glasgow Surveyors be requested to forward the boiler plan of this vessel, as it does not appear to have been received in this office.

JWD
 26/10/44
 PMS

002750-002753-0130

ze of compensating ring *20 X 24 X 1 1/2* No. and Description of Furnaces in each Boiler *Wing* material *S*
 length of plain part top *✓* crown *4 3/4"* Thickness of plates bottom *✓* Description of longitudinal joint *Weld* No. of stren
 orking pressure of furnace by the rules *257* Combustion chamber plates: Material *S* Thickness: Sides *23/32* Back *21/32* Wing *25/32*