



CLASSIFICATION.


"EL. LIBERTADOR".
Electrical Installation.

The Builders' Electrical Specification has been examined and the installation appears to meet the requirement of the Rules. In view also of the age of the installation and the satisfactory report (No. 2077) issued by the Mobile Surveyors ^{on} and the condition of the installation, It is considered the installation is eligible for the classification proposed.


2.10.44.









© 2021

Lloyd's Register
Foundation

002762-002769-0019